

**Department for Environmental Protection Kentucky Division of Waste Management** 

> November 3, 2016 Presented by Chris Jung



To Protect and Enhance Kentucky's Environment




### **Site Location**





# **Bosch Tool**













# **History of the Facility**



Kentucky NO SPIRITY

#### HISTORY OF FACILITY

- In 1970, Vermont American Corporation manufactured screw driver bits, drill bits, circular saw blades, and hedge trimmers (1986 to 1996).
- In 1974, Bosch expanded the building from 43,000 to 86,000 square feet.
- In 1989, the Vermont American Corporation was acquired by the Robert Bosch Corporation and Emerson Electric and officially became the Robert Bosch Tool Corporation in 2003.
- In 2004, Bosch Tool ceased all production at the Leitchfield facility and it was unoccupied until 2010.
- In 2010, the property was sold and is currently used as a storage warehouse.





#### **PRIMARY WASTES GENERATED AT THE FACILITY**

- ➤ Trichloroethylene (TCE)
- ▶1,1,1,-Trichlorethane (111-TCA)
- ➤ Chrome and Nickel Plating Sludges
- ➤ Sodium Hydroxide (NaOH)
- ▶Potassium and Sodium Nitrate



Kentucky NO SPIRIT

## Initial Environmental Investigations

- In 1991, excavation material impacted by TCE was discovered. Fifty tons of material was excavated and disposed of offsite.
- In 2004, phase I and II environmental investigations were performed. The phase II concluded that exceedances in the soil and groundwater were present.





# **Groundwater Investigation**



Division of Waste Management

Kentucky

## **Groundwater Chemicals of Concern**

- Trichoroethylene (TCE)
- Cis-1,2-Dichloroethene (cis-1,2 DCE)
- Vinyl Chloride (VC)



Kentucky LINERIDLED SPIRITY

# **Groundwater Investigation**

- 38 permanent monitoring wells
- 12 remediation test wells
- 3 former water supply wells:
  - PW-1
  - PW-2
  - Kiper Well (offsite)



Kentucky WINDERD SPIRITY

## **Groundwater Sampling Results**


The highest recorded monitoring well concentrations during the November 2015 sampling event were found in MW-5/MW-5M:

- TCE at 2.77 ppm (MCL .005 ppm)
- cis-1,2-DCE at 2.09 ppm (MCL .07 ppm)
- VC at 1.79 ppm (MCL .002 ppm)





















## **Air Investigation**



Kentucky







#### **Crawl Space Air Sampling**

- In 2012, crawl space sampling was conducted at the Barton property.
- Three locations were selected, and an 8-hour test was conducted.
- The highest recorded sample result was 2.0 µg/m³ TCE.
- Highest follow-up results was .83 μg/m³.








### **Indoor Air Facility Samples**

- Four locations were selected, and an 8-hour test was conducted.
- The highest recorded sample result was 13.4 μg/m³ TCE.







# Trichloroethylene (TCE)

• EPA Region 9 Interim TCE Indoor Air Response Levels:

**▶**Residential

 $2 \mu g/m^3$ 

Commercial/Industrial (10-hour workday)

 $7 \mu g/m^3$ 

Commercial/Industrial (8-hour workday)

 $8 \mu g/m^3$ 





# Remediation



Division of Waste Management

Kentucky


UNBRIDLED SPIRIT

#### Remediation

- Based on the elevated sample results, Bosch Tool implemented remediation in 2012.
- Injection of a reductive dechlorinator (BOS 100) into source area.
- Injection of biostimulates (3DMe) into less concentrated plume area.































#### **Next Phase**









Division of Waste Management 300 Sower Boulevard Frankfort, KY 40601 Point of contact: Tina Fisher

(502)782-6357

Email: tina.fisher@ky.gov

Grayson County Public Library
130 E. Market Street
Leitchfield, KY 42754

